



Pace Analytical Services, Inc.
1000 Riverbend Blvd. Suite F
St. Rose, LA. 70087
(504) 469-0333

October 18, 2010

Reynaldo Matos Jimenez
PR Environmental Quality Board
PO Box 11488
San Juan, PR 00910

RE: Project 20114876
Project ID: ASHES CHARACTERIZATION

Dear Reynaldo Matos Jimenez:

Enclosed are the analytical results for sample(s) received by the laboratory on October 08, 2010. Results reported herein conform to the most current NELAC standards, where applicable, unless otherwise narrated in the body of the report.

If you have any questions concerning this report, please feel free to contact me.

Sincerely,

A handwritten signature in black ink, appearing to read "Juan Redondo", with a long, sweeping horizontal line extending to the right.

Juan Redondo
juan.redondo@pacelabs.com



REPORT OF LABORATORY ANALYSIS

This report shall not be reproduced, except in full, without
the written consent of Pace Analytical Services, Inc.

Cover 10/18/2010 09:09:35



Laboratory Certifications

Pace Analytical Services, Inc.
1000 Riverbend Blvd. Suite F
St. Rose, LA 70087
(504) 469-0333

Project: 20114876

Client: PR Environmental Quality Board

Project ID: ASHES CHARACTERIZATION

Washington Department of Ecology C2078
Oregon Environmental Laboratory Accreditation - LA200001
U.S. Dept. of Agriculture Foreign Soil Import P330-10-00119
Pennsylvania Dept. of Env Protection (NELAC) 68-04202
Texas Commission on Env. Quality (NELAC) T104704405-09-TX
Kansas Department of Health and Environment (NELAC) E-10266
Florida Department of Health (NELAC) E87595
Louisiana Dept. of Health and Hospitals (NELAC) LA100024
Louisiana Dept. of Environmental Quality (NELAC/LELAP) 02006

10/18/2010 09:09:36



REPORT OF LABORATORY ANALYSIS

This report shall not be reproduced, except in full, without
the written consent of Pace Analytical Services, Inc.